

## CERTIFICATE

No. Z2 053696 2473 Rev. 00

**Holder of Certificate:** 

KOMPAN A/S

C.F. Tietgens Boulevard 32C 5220 Odense SØ

**DENMARK** 

**Certification Mark:** 



## **Product:**

## Merry-go-round

The product was tested on a voluntary basis and complies with the essential requirements. The certification mark shown above can be affixed on the product. It is not permitted to alter the certification mark in any way. In addition the certification holder must not transfer the certificate to third parties. See also notes overleaf.

Test report no.:

713150089-20

Valid until:

2024-10-10

Date,

2019-11-20

( Michael Weber )



## CERTIFICATE

No. Z2 053696 2473 Rev. 00

Model(s):

GXY916000, GXY916012, GXY916032, GXY944000,

GXY944012, KPL114, NRO109, NRO120

**Parameters:** 

GXY916000, GXY916012, GXY916032, GXY944000, GXY944012: Track run carousel. A closed PE-Ring is mounted on a steel rail.

The rail is anchored in the ground by five pillars.

Pillars. Ø: 2.08 m Max. height: 60 cm

The models GXY916000, GXY916012 have a 10° Inclination.

KPL114:

Carousel with closed platform, benches, side barrier, and centre wheel.

Floor made of aluminium plate.

Tubes of the top frame made of Ø33.7 mm.

Benches: 19 mm HDPE Carousel diameter: 1.55 m

NRO109, NRO120:

Wooden platform with an three sided middle assembly made of

three poles and a top plate with three handles.

Tested

DIN EN 1176-1:2017 DIN EN 1176-5:2008 EN 1176-1:2017

EN 1176-5:2008

according to:

Production Facility(ies):

063062

Allh